


VI SEMESTER B.TECH. (INDUSTRIAL AND PRODUCTION ENGINEERING)
END SEMESTER EXAMINATIONS, APRIL 2018
SUBJECT: QUALITY CONTROL AND RELIABILITY ENGINEERING
[MME 3212]
REVISED CREDIT SYSTEM

Time: 3 Hours

MAX. MARKS: 50

Instructions to Candidates:

- ❖ Answer **ALL** the questions.
- ❖ Missing data may be suitably assumed.
- ❖ Use of SQC tables permitted.

1A. Explain the effect of assignable causes on a process. **(02)**
1B. Explain the inequality theorems. **(03)**
1C. Calculate mean, standard deviation, median and mode for the following frequency distribution:

Characteristic value	3	6	9	12	15	18	21
Frequency	4	7	10	15	9	8	7

(05)
2A. What is Type II error with regard to control charts? How it is minimized? **(02)**
2B. Explain the graphical methods of representing a frequency distribution. **(03)**
2C. Samples of 6 items are taken from a manufacturing process at regular intervals. A normally distributed quality characteristic is measured and \bar{X} and s values are calculated for each sample. After 50 subgroups have been analyzed, we have $\sum \bar{X} = 1000$ and $\sum s = 75$.

- (i) Calculate 3 sigma control limits for \bar{X} and s control charts.
- (ii) Assume that all points on both charts fall within the control limits. Compute the Natural tolerance and Natural tolerance limits of the process.
- (iii) If the specification limits are 19.0 ± 4.0 , what percentage of product does not meet the specifications? **(05)**

- 3A.** Write a note on system reliability. (03)
- 3B.** Explain the control charts for fraction rejected and rejects. (03)
- 3C.** A c chart is used to monitor the number of nonconformities on sheets of photographic film. The chart is presently set up based on \bar{c} of 2.6.
- (i) Find 3 sigma control limits for this process.
 - (ii) Use Poisson's distribution table to determine the probability that a point will fall outside these limits while the process is actually operating at a μ_c of 2.6.
 - (iii) If the process average shifts to 4.8, what is the probability of not detecting the shift? (04)
- 4A.** Explain (i) AQL (ii) AFI (iii) AOQL (03)
- 4B.** With a neat sketch explain the Normal curve. How it is useful in quality control? (03)
- 4C.** A double sampling plan is as follows:
- $$n_1 = 150, c_1 = 2, n_2 = 300, c_2 = 3.$$
- Assuming the lot size is large in comparison to sample size, compute the probability of acceptance of a 2% defective lot. (04)
- 5A.** Explain the theory of extreme runs of points. (03)
- 5B.** Write a note on O.C. Curve. (03)
- 5C.** Two mating parts A and B have normal distributions and are assembled at random. The standard deviations of the dimensions A and B are 0.0025 inch and 0.0075 inch respectively. What should be the average clearance if the probability of interference between the parts should not exceed 0.001? (04)