

# IV SEMESTER B. TECH (INDUSTRIAL & PRODUCTION ENGINEERING) END SEMESTER (GRADE IMPROVEMENT) EXAMINATION, AUGUST 2021 SUBJECT: MANUFACTURING AUTOMATION ENGINEERING (MME 2256) REVISED CREDIT SYSTEM

Time: 120 Minutes MAX. MARKS: 40

Note: Answer ANY FOUR FULL questions.


- 1A A double acting cylinder guides cylinder pins towards a measuring device.

  The pins are separated by means of a continuous to and fro movement. The oscillating motion can be started by means of a valve with selector switch. The duration of forward stroke and return stroke of the cylinder is to be adjustable.

  The cylinder is to remain in the forward end position for t = 5 seconds. Design a pneumatic circuit to automate the process.
- 1B With a neat sketch explain the working of a pneumatic pressure regulator. 3
- 1C With a neat sketch explain the construction and working of a 3/2 direction 3 control valve used in pneumatic systems.
- 2A A station uses conveyor system to check the presence of lids on cans. If a can without a lid is encountered, then the can must be pushed aside from the conveyor into a bin by a pneumatic cylinder. The lids and cans are interrogated by means of sensors. Design an electro pneumatic circuit for the process.
- 2B With the help of electro pneumatic circuit explain the latching circuit. 3
- 2C Identify and explain with a neat sketch the working of the component used in electro pneumatic systems which is used to detect the advanced and retracted end positions of the piston rod in linear actuators.

MME 2256 Page **1** of **3** 

- 3A An electro pneumatic system requires a sensor to detect the presence of nonmetallic parts in the shop floor. Identify and explain the working of the component with the help of a neat sketch.
- 3B With the help of a pneumatic circuit explain the working of a one-way flow control valve.
- 3C What are the advantages of using compressed air in pneumatic systems? 3
- 4A With a neat sketch explain cylindrical and tapered roller bearing. 4
- 4B List and explain any three types of material handling equipment. 3
- 4C Sketch and explain loop layout group machine cell with semi integrated **3** handling system.
- 5A Write a CNC part program for the workpiece shown in Fig. 1.




2. Use grooving tool width 3 mm

Figure 1

- 5B List and explain Flexible Manufacturing System data files. 3
- 5C With a neat sketch explain the working of timing belt. 3
- 6A Write a short note on Material Requirement Planning. 4
- 6B Write a short note on multi-class part classification and coding system. 3

MME 2256 Page **2** of **3** 



Tools to be used: 1.Ø 20 mm end mill 2.Ø 5 mm drill tool

Figure 2

MME 2256 Page **3** of **3** 

# MME 2256: Manufacturing Automation Engineering

## 1. Hydraulic systems

1.1. Force on the piston in a linear actuator (piston cylinder assembly)

$$\begin{aligned} \mathsf{F_E} &= p * A_P \\ p &= \mathsf{fluid} \; \mathsf{pressure} \; (\mathsf{N}) \\ p_R &= p * (A_P - A_R) \end{aligned}$$
 
$$\begin{aligned} F_R &= p * (A_P - A_R) \\ A_P &= \frac{\pi D_P^2}{4} \; \mathsf{piston} \; \mathsf{area} \; (\mathsf{m}^2) \\ A_R &= \frac{\pi D_R^2}{4} \; \mathsf{prod} \; \mathsf{area} \; (\mathsf{m}^2) \\ D_P \; \& \; D_R \; \mathsf{piston} \; \mathsf{and} \; \mathsf{rod} \; \mathsf{diameter} \; (\mathsf{m}) \end{aligned}$$

1.2. Velocity of piston in a linear actuator

$$V_{\rm E} = \frac{Q}{1000*A_P}$$

$$V_{\rm E} \& V_{\rm R} = \text{velocity of extension and retraction of the piston (m/min)}$$

$$Q = \text{Discharge (lpm)}$$

$$A_P = \frac{\pi D_P^2}{4} = \text{piston area (m}^2)$$

$$A_R = \frac{\pi D_R^2}{4} = \text{rod area (m}^2)$$

$$D_P \& D_R = \text{piston and rod diameter (m)}$$

1.3. Power generated by the actuator (kW)

Power = 
$$\frac{F*v}{1000}$$
  $F = Force (N)$   
 $v = velocity (m/s)$ 

### 2. Computer Numerical Control and programming

2.1. Codes for Turning Centre

| G Codes                            | M Codes                          |
|------------------------------------|----------------------------------|
| G00 - POSITIONING (RAPID TRAVERSE) | M00 - PROGRAM STOP               |
| G01 - LINEAR INTERPOLATION (FEED)  | M01 - OPTIONAL STOP              |
| G02 - CIRCULAR INTERPOLATION (CW)  | M02 - PROGRAM RESET              |
| G03 - CIRCULAR INTERPOLATION (ACW) | M03 - SPINDLE FORWARD            |
| G20 - INCH DATA INPUT              | M04 - SPINDLE REVERSE            |
| G21 - METRIC DATA INPUT            | M05 - SPINDLE STOP               |
| G28 - REFERENCE POINT RETURN       | M06 - AUTO TOOL CHANGE           |
| G70 - FINISHING CYCLE              | M08 - COOLANT ON                 |
| G71 - STOCK REMOVAL IN TURNING     | M09 - COOLANT OFF                |
| G72 - STOCK REMOVAL IN FACING      | M13 - SPINDLE FORWARD COOLANT ON |
| G73 - PATTERN REPEATING            | M14 - SPINDLE REVERSE COOLANT ON |
| G74 - PECK DRILLING                | M30 - PROGRAM RESET REWIND       |
| G76 - THREAD CUTTING CYCLE         | M38 - DOOR OPEN                  |
| G90 - TURNING CYCLE                | M39 - DOOR CLOSE                 |
| G94 - FACING CYLCE                 | M98 - SUB PROGRAM CALL           |
| G98 - FEED PER MINUTE              | M99 - SUB PROGRAM END            |
| G99 - FEED PER REVOLUTION          |                                  |

# 2.2. Codes for Vertical Machining Centre

| G Codes                                | M Codes                          |
|--|----------------------------------|
| G00 - POSITIONING (RAPID TRAVERSE)     | M00 - PROGRAM STOP               |
| G01 - LINEAR INTERPOLATION (FEED)      | M02 - PROGRAM RESET              |
| G02 - CIRCULAR INTERPOLATION (CW)      | M03 - SPINDLE FORWARD            |
| G03 - CIRCULAR INTERPOLATION (ACW)     | M04 - SPINDLE REVERSE            |
| G20 - INCH DATA INPUT                  | M05 - SPINDLE STOP               |
| G21 - METRIC DATA INPUT                | M06 - AUTO TOOL CHANGE           |
| G28 - REFERENCE POINT RETURN           | M08 - COOLANT ON                 |
| G40 - TOOL NOSE RADIUS                 | M09 - COOLANT OFF                |
| COMPENSATION                           | M13 - SPINDLE FORWARD COOLANT ON |
| CANCEL                                 | M14 - SPINDLE REVERSE COOLANT ON |
| G41 - TOOL NOSE RADIUS                 | M30 - PROGRAM RESET & REWIND     |
| COMPENSATION                           | M38 - DOOR OPEN                  |
| LEFT                                   | M39 - DOOR CLOSE                 |
| G42 - TOOL NOSE RADIUS                 | M70 - MIRROR ALONG X ON          |
| COMPENSATION                           | M71 - MIRROR ALONG Y ON          |
| RIGHT                                  | M80 - MIRROR ALONG X OFF         |
| G68 - CO-ORDINATE ROTATION             | M81 - MIRROR ALONG Y OFF         |
| G69 - CO-ORDINATE ROTATION CANCEL      |                                  |
| G73 - PECK DRILLING CYCLE              |                                  |
| G76 - FINE BORING                      |                                  |
| G80 - CANNED CYCLE CANCEL              |                                  |
| G81 - DRILLING CYCLE                   |                                  |
| G82 - DRILLING CYCLE, COUNTER          |                                  |
| BORING                                 |                                  |
| G84 - TAPPING CYCLE                    |                                  |
| G90 - ABSOLUTE DIMENSIONING            |                                  |
| G91 - INCREMENTAL COMMAND              |                                  |
| G94 - FEED PER MINUTE                  |                                  |
| G95 - FEED PER REVOLUTION              |                                  |
| G98 - RETURN TO INITIAL POINT IN       |                                  |
| CANNED CYCLE                           |                                  |
| G99 - RETURN TO R (Reference point) IN |                                  |
| CANNED CYCLE                           |                                  |